

0098

From: "Gefferth, John" <JohnGefferth@consolenergy.com>
To: "Pam Grubaugh-Littig" <pamgrubaughlittig@utah.gov>, "Steve Christensen" ...
Date: 12/6/2007 9:39 AM
Subject: Emery Groundwater, surface water deficiency
Attachments: emgw.dogm.titleblk.pdf; emgwtblVI17.pdf; Table VI-17 rev.pdf

Pam/Steve

*incoming of
4/015/0015*

The attached pdf, emgw.dogm.titleblk.pdf (Plate VI-4, GW and Surface water monitoring site map) answers the deficiency by explaining in the legend the sample parameters of both groundwater and surface sites.

To determine what parameters are required at a particular sample site you need the map and table VI-17 (emgwtblVI17.pdf)....Table VI-17 outlines the parameters for surface water sites, ground water sites, and UPDES sites..

Consol was under the impression that this Plate and table were adequate to answer the deficiency.

After talking to Steve yesterday afternoon, we added a listing of the sample sites to Table VI-17 (Table VI-17 rev.pdf) The block in red is what was added this morning.

All of the required data was included in the submittal , the added listing is redundant due to the fact that it was on the Plate.

John Gefferth

Consol Energy

P.O. Box 566

Sesser, Illinois 62884

618-625-6850 office

618-534-5151 cell

618-625-6844 fax

www.consolenergy.com <<http://www.consolenergy.com>>

----- "This communication,
including any attachments, may contain confidential and privileged
information that is subject to the CONSOL Energy Inc.'s Business
Information Protection Policy. The information is intended solely
for the use of the intended recipient(s). If you are not an
intended recipient, you are prohibited from any use, distribution,
or copying of this communication. If you have received this
communication in error, please immediately notify the sender and
then delete this communication in its entirety from your system."